



Worn out top surface



Smooth finish through LANKO 783

> Waterproofing Systems and Technical Solutions



> It Park - Car Parking Repair

Car parking area which was constructed three years ago using IPS (Indian patent stone) flooring, observed weathering off top layer due to low strength and continuous vehicular movement.

The contractor was to break the entire surface and redo it from scratch before getting in touch with PAREX India.

With a simpler solution in mind, PAREX India did a sample of 2 meter sq which was put under observation for a month. It was approved and work order being released.

Jobsite was executed over weekend and traffic was open to movement on Monday morning. Finishing given with scratch lines to ensure anti-skidding.

APPLIED PRODUCT



TECHNICAL DETAILS

- Surface : 6,000 m²
- Volume : 27 Tons of LANKO 783
175Kg LANKO 162

> LOCATION

Bangalore – Karnataka - India

> CUSTOMER

Indiqube software park

> MARKET SEGMENT

Concrete Repair

> SUBSEGMENT FUNCTION

Surface Treatment

> YEAR

2015

BRAND

LANKO

PAREX
Building expertise, together